November 18, 2009 12:37:31 PM

Item ID:

D2570

Bushing

R

Required Date: 25/11/2009

Revision ID: Item Name:

Start Date:

18/11/2009

Start Oty: 400.00 Rea'd Otv: 400.00



Accept



Setup Start



Referenca:

Approvals:

Process Plan:

Date: 07-11-18

Date:

Tooling: **SPC (Y/N):**  Date:

Date:

Run

Start



Stop

Sequence ID/ Work Center ID Operation Description Set Up/ Run Hours

Draw Number

**Cust Item ID:** 

**Customer:** 

Draw Rev.

Plan Accept Code Qty

Reject Qty

Reject Number

Insp. Stamp

Draw Nbr

**Revision Nbr** 

D2570

Rev B

100

Hardinge

Hardinge CNC Lathe Small

Hardinge CNC LATHE SMALL

Memo

Machine as per folio FA258□Deburr

000000

110

Quality Control

QC2- Inspect parts off machine FAI/FAIB

Memo

0.00 Sto 9121d

0.00

120

Quality Control

QC8- Inspect parts - second check

Memo

0.00

0.00

415

Dart Aer	ospace	Ltd
----------	--------	-----

	•								•
W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				,					
					·				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date:	
		esolution:							
NCR:	·			ER NON-CONFORM					
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sect Action Description	ion B		cation	Approval	Approval
		JEGIOTI A	Chief Eng	Chief Eng	Dat		on C	Chief Eng	QC Inspector
				<u>, , , , , , , , , , , , , , , , , , , </u>			,		
		·							
		*							
									L

NOTE: Date & initial all entries

#### Work Order ID 53778

Page 2

November 18, 2009 12:37:31 PM

Item ID:

D2570

Bushing

В

**Revision ID:** Item Name:

**Start Date:** 

18/11/2009

Start Qty: 400.00 Req'd Qty: 400.00 **Required Date: 25/11/2009** 

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date:

Tooling:

Accept

SPC (Y/N):

**Run Hours** 

Set Up/

Draw

Date:

Date:

Draw

Rev.

Run

Setup Start

Start

Stop

Stop



Sequence ID/ Work Center ID

130

Packaging

Packaging

Operation Description

Identify as per dwg & Stock Location:\_ 57

QC: Date:

Memo

Memo

0.00

0.00

Number

Plan Code Accept Qty

Reject Qty

Reject Number Stamp

Insp.

UNF 09-12-18

140

Quality Control

OC21- Final Inspection - Work Order Release

0.00

0.00

# **Dart Aerospace Ltd**

W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CHA		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
								<u> </u>	
<u>-</u>							. z é		
								ĺ	
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	•	Date:	
<u>.</u>		esolution:							
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	₹)			/
DATE	STEP	Description of NC		Corrective Action Section		Verifica	ation	Approval	Approval
DATE	SIEF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign a	Section		Chief Eng	QC Inspector

NOTE: Date & initial all entries

### **Picklist Print**

November 18, 2009 12:37:47 PM

Work Order ID: 53778

Parent Item:

D2570RevB

Parent Item Name: Bushing



Start Date: 18/11/2009

Required Date: 25/11/2009

Page 1

**Start Qty: 400.00** 

Required Qty: 400.00

<b>Component Item</b>	ID/
Item Name	

Replacement Mfg/ Item ID

Purch

Primary Bin Item Location

Last Location Route Seq ID Unit of Qty on Measure Hand

Remaining Qty To Pick Issued

Qty

Date. Status Issued

M303R0.750

Comments:

Purchased

No

100

f

108.1000 32.4632

Loc Code



303 Round Bar 0.750

Warehouse Loc Qty Location Main Warehouse MAT 108.1

107077 113134

0 108.1

MF 09-18-18

<b>Dart</b>	<b>Aeros</b>	pace	Ltd
-------------	--------------	------	-----

W/O:		***************************************	WO	RK ORDER CHANG	GES			-		·
DATE	STEP PROCEDURE CHANGE By				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
	<u> </u>									
								į	•	
				-						
Part No	•	PAR #:	Fault Categ	jory:	NCI	R: Yes	No DQ	<b>A</b> :	Date:	
	R	esolution:	Disposition	1:	QA	N/C CIG	sed:		Date: _	
NCR:		1	WORK ORDE	R NON-CONFORM	ANCE	(NCR	)			<u> </u>
DATE	STEP	Description of NC	Description of NC Corrective Action			Section B			Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector
										1
					***************************************					
		,								
								-		

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	53778
Description: Bushing	Part Number:	D2570
Inspection Dwg: D2570 Rev: B		Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

	>	First Art	icle	Prot	otype
Drawing	Tolerance	Actual	Accept	Reject	Method
	loierance	l <b>5</b>	Accept	Velect	Inspection


Drawing	Tolerance	Actual	Accept	Accept Reject		Comments
Dimension	1010.2	Dimension			Inspection	
0.800	+/-0.010	801				
0.060	+/-0.005	.062				
R0.010	+0.010/-0.000	R.015				
Ø0.425	+0.000/-0.002	0.427				
Ø0.257	+0.006/-0.001	2259	1/			
Ø0.750	+/-0.010	0.745				
0.030 x 20°	+/-0.010	OBXJOO				
				_		
	-					
			<u></u>			
	·					


Measured by:	Audited by:	WV-	Prototype Approval:	N/A
Date: SVIDIO	Date:	alleva	Date:	

Rev	Date	Change	Revised by	Approved
A	03.12.08	New Issue	KJ/RF	
В	04.02.23	Tolerance for Ø0.425 changed	KJ/RF	
C	07.07.17	Dimensions updated per Dwg Rev. B	KJ/JLM 1/A	
D	08.07.23	Tolerance for Ø0.257 revised	KJ/DD C	



0500			<del>                                     </del>
DESIG	PH	DRAWN BY	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA
CHEC	KED ad	APPROVED J	DRAWING NO. REV.
	世	91	D2570 SHEET 1 OF
DATE			TITLE SCALI
07.0	04.17		BUSHING 1:
Α		96.09.16	NEW ISSUE
В		07.04.17	UPDATE NOTES





# D2570 BUSHING

D2570 BUSHING

MATERIAL: 1)

AISI 303 ROUND BAR (REF. DART SPEC. M303R)

2) = FINISH:

NONE-

- 3) ALL DIMENSIONS ARE INCHES
- TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED 4)
- BREAK ALL UNMARKED SHARP EDGES TO 0.010 MAX 5)

SUBJECT . With a

\* + 4 L L

UNC . .

Copyright © 1996 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.